

DGW Release Notes v

45.1.1870
2019-10-31


Table of Contents

Firmware Pack	3
New Functionalities	4
Modified Features, Functionalities and Interface Modifications	5
Copyright Notice	6

Firmware Pack

The firmware pack is a binary file that contains the modules and the features to install on your Mediatrix unit when a new release is available.

New Functionalities

Incident #	CR #	Synopsis	Applies To
Description			
	DGW-11598	Support licence for the Estimated MOS feature	all
Added support for the new Voice Quality Estimation (eMOS) Licence enabling the new Estimated MOS feature.			
	DGW-11245	Support RFC 6035 to send media metrics report via SIP PUBLISH request.	SIP
Added the support of the session and interval report as defined in RFC 6035. The feature can be activated with the following new parameters: - SipEp.DefaultStaticRtcpXrCollectorUri - DefaultRtcpXrPeriodicReportsInterval, - SipEp.GwSpecificRtcpXr.CollectorUri - SipEp.GwSpecificRtcpXr.PeriodicReportsInterval The new parameters are available under SIP/Misc of the DGW Web Interface.			
			
---	DGW-10516	Add support for factory-installed Vm in Vm service.	Vm
Vm service now supports the factory-installed Vm feature. A factory reset will delete all vm images under vm/images and will create a new snapshot from the factory-installed Vm.			
---	DGW-10338	Increase the "Other" certificate limit from 10 to 20.	all
The limit of "Other" certificates that can be present on a unit has been increased to 20.			

Modified Features, Functionalities and Interface Modifications

Incident #	CR #	Synopsis	Applies To
Description			
IN-14230	DGW-11227	Ringback tone is not heard in SIP to ISDN calls.	all
The following parameters no longer have an impact on incoming ISDN calls: - Isdn.PrimaryRateInterfaceInterop.UseImplicitInbandInfoEnable - Isdn.BasicRateInterfaceInterop.UseImplicitInbandInfoEnable			
---	DGW-10516	Add support for factory-installed Vm in Vm service.	Vm
Vm service now supports factory-installed Vm feature. A factory reset will delete all vm image under vm/images and will create a new snapshot from the factory-installed Vm.			
---	DGW-10338	Increase the "Other" certificate limit from 10 to 20.	all
"Other" certificate limit has been increased to 20.			

Copyright Notice

Copyright © 2019 Media5 Corporation.

This document contains information that is proprietary to Media5 Corporation.

Media5 Corporation reserves all rights to this document as well as to the Intellectual Property of the document and the technology and know-how that it includes and represents.

This publication cannot be reproduced, neither in whole nor in part, in any form whatsoever, without written prior approval by Media5 Corporation.

Media5 Corporation reserves the right to revise this publication and make changes at any time and without the obligation to notify any person and/or entity of such revisions and/or changes.





4229, rue de la Garlock
Sherbrooke (Quebec)
J1L 2C8 Canada
media5corp.com